

FITNESS CERTIFICATE

TO BE FILLED BY THE INSPECTING OFFICER(ASSISTANT ENGINEER)

(Re:G.O.Ms.20/70/PWD Dt.23-01-1970)

No: AE/LID&EW/MEP/FIT/01/2025-26

Date: 21/04/2025

- | | | |
|---|---|----------------------------|
| 1. Name of School | : | MOUNT TABOR ENGLISH SCHOOL |
| 2. Name of Officer | : | JOHNY J BOSCO |
| 3. Location | : | KALPETTA--MEPPADI Road |
| 4. Period for which the certificate is issued | : | 2025-26 Academic Year |
| 5. Type of Building | : | |
| 6. Nature of defect if any | : | Nil |

CLASSIFICATION OF BUILDING :

BLOCK NO.1(Near road side) : 23.25x7.65 X4.15- GF -3 classroom
(4 FLOORS) with top floor Sandwich sheet roofing
27.90X8.31X3.82 - FF -3 classrooms+staff room -
27.90X8.31X3.82 -SF Compt, Language Lab&1 class room-
27.90X8.31X3.82 - TF-- Hall-


BLOCK NO.2(RCC 4 FLOORS) : 32.70X11.95X3.70 -GF Office+ Chappel block-
32.70X11.95X3.70 -FF 4 classrooms +staff room
32.70X11.95X3.70 -CF 1—2 class rooms+ Sciencelab
32.70X11.95X3.70 -CF 2—2 class rooms+ Library

BLOCK NO.3(RCC4 FLOORS) : 21.90 X8.6X3.80 - GF - 3 class rooms
21.90 X8.6X3.80 - FF—3 class rooms
13.10X8.50X3.8 -GF—1 classroom
13.10X8.50X3.8 -CF 1—1 classroom
13.10X8.50X3.8 -CF 2—1 classroom
8.45X4.70X3.8 - GF-- Stage
8.45X4.70X3.8 - FF

- | | | |
|--|---|------------------|
| a) Foundation & Basement | : | RCC |
| b) Superstructure | : | |
| c) Doors & Windows | : | |
| d) Wood work wrought and put up | : | |
| e) Roof | : | |
| f) Flooring | : | CEMENT PLASTERED |
| g) Miscellaneous | : | |
| 7. Any major defect notice which will render the building unsafe in any manner | : | Nil |
| 8. Whether maintains work have been done properly | : | Yes |


PRINCIPAL
MOUNT TABOR ENGLISH SCHOOL
MEPPADI, WAYANAD
PIN:673577




MANAGER
MOUNT TABOR ENGLISH SCHOOL
MEPPADY, WAYANAD
PIN : 673577

9. Whether the structure sound for conducting classes

: Yes, Safe under normal condition

Note: 1. The stability of the structure should be examined also with reference to the altitude intensity of wind exposure to flood etc.

2. Any additional observation if deemed necessary for certificate may be furnished separately with the certificate

Certified that the school was inspected by me on 21/04/2025 and found to be fit to be conduct classes for the period for the reasons stated above.

Place : Meppadi

Date : 21/04/2025



Signature

Designation

PEN-458415

Assistant Engineer
LSGD Section

Meppadi Grama Panchayath

PRINCIPAL
MOUNT TABOR ENGLISH SCHOOL
MEPPADI, WAYANAD
PIN:673577



MANAGER
MOUNT TABOR ENGLISH SCHOOL
MEPPADI, WAYANAD
PIN:673577